OILPATH

OP101

DOUBLE LOCK VALVE





OP 101/I

For insertion in hose lines between control valve and double acting cylinder

OP 101/C


For direct mounting to double acting cylinder base port and via metal tubeline to gland port


Features:


- Manufactured from aluminium alloy
- Hardened steel check seats
- Pilot spool area to check seat area ratio 3:1
- Flow capacity up to 12 gpm (54 litres)
- Working pressure up to 3000 psi (20.68 MPa)
- Standard port size 1/2" BSP-T


Schematic

Cutaway view and parts diagram shown for model OP101/C. For model OP101/I replace 3/4" JIC nipple (11) with 1 1/6" plug (1) and remove port plug (10).









| Ref. | Part | Item | Ref. | Part | Item |
|------|-------|---------------|------|--------|------------------|
| 1 | 101-1 | 1%" UNF plug | 7 | 101-7 | Piston |
| 2 | 101-2 | O-ring, BS119 | 8 | 101-8 | O-ring, BS113 |
| 3 | 101-3 | Spring | 9 | 101-9 | Body |
| 4 | 101-4 | Ball, 1/2" | 10 | 101-10 | Plug, 1/2" BSP-T |
| 5 | 101-5 | Seat cage | 11 | 101-11 | Nipple, 3/4" JIC |
| 6 | 101-6 | O-ring, BS116 | | | |

Options (available on special order)

- 3/4" UNF O-ring 16 TPI ports
- 3/8" BSP-T ports
- · Piston fitted with O-ring

Warranty

Oilpath products are warranted to be free of defects in material or workmanship.

This Warranty voids all other warranties, whether expressed or impiled, and shall be in effect for six months.

The Warranty is limited to replacement or repair, excluding seals or damage arising from misuse or incorrect litting.

The Company accepts no liability for faults caused by improper use or faulty maintenance of the product, or its operation beyond recommended specifications or contingent or consequential loss or damage under any situation whatsoever.

All unauthorised modifications to the product automatically voids the conditions of this Warranty.

Manufactured by:

PATH INC. IN SOUTH AUSTRALIA A.B.N. 97 007 683 472

21 Deloraine Road, Edwardstown, South Australia. PO Box 132, Edwardstown 5039 Ph: (08) 8277 4933 Fax: (08) 8277 9126